

All System Diagnostic Report

01-11-2024 14:21:39

TC0021675585

VEHICLE INFORMATION



WBA21EJ050CP08063

Make	BMW
Model	7 Модельный ряд
Year	2006.11

INSPECTION RESULT

- There are 1 issues for Vehicle body system
1,Микрофон: драйвер микрофона не откалиброван
- Inspections are normal for Vehicle body system
1,ULF-SBX-H (Interface Box High)



PROFESSIONAL REPORT

- AMP (Усилитель) ^

Version Information

DTC Qty (1)

B7F500

Микрофон: драйвер микрофона не откалиброван

ThinkGPT

Permanent

Live data Qty (0)

- ULF-SBX-H (Interface Box High) v